



FEBRUARY 25TH STORM UPDATE

Novato Creek Washout


SMART Board of Directors Meeting

March 6, 2019

FEBRUARY 25TH STORM



NOVATO CREEK WASHOUT – FEB 14TH



NOVATO CREEK WASHOUT – FEB 14TH



Photo taken on February 14, 2019

WASHOUT REPAIR – FEB 14TH



WASHOUT REPAIR



WASHOUT REPAIR – FEB 14TH



FEBRUARY 25TH WASHOUT



FEBRUARY 25TH – LEVEE BREAK



FEBRUARY 25TH FLOODING



FEBRUARY 25TH FLOODING



FEBRUARY 25TH FLOODING

A SMART train travels through a flooded portion of the track.



FEBRUARY 25TH STORM DAMAGE

Next Steps:

- Raise Track
- Restore Site
- Monitor through the rest of Winter

